

Personal Protective Equipment REQUIREMENTS



Safety Glasses

AS/NZS 1337 compliant.
Worn at all times while on site in operational zones. Prescription glasses must also meet the requirements of AS/NZS 1337.



Hi-Vis Clothing

AS/NZS 4602 compliant
Vest, shirt, windcheater or jackets. Must be buttoned or zipped up at all times.



Protective Hard Hat

AS/NZS 1801 compliant.
Worn at all times while on site in operational zones.
Damaged hard hats are to be disposed of.



Protective Footwear

AS/NZS 2210 compliant.
Worn at all times while on site in operational zones. Must be laced or zipped-up correctly.



Long Sleeve Top & Full Length Pants


Worn at all times while on site in operational zones. Protection from physical, chemical, and environmental hazards, including UV.



Gloves

AS/NZS 2161 compliant. Must be carried on person at all times on site.
Worn for all manual handling tasks.
Assess task and match gloves to suit.*

*For general purpose gloves, the minimum cut rating is 3 (EN388:2003), or C (EN388:2016).



Note 1: PPE must be in good repair, worn appropriately and used in accordance with manufacturer's requirements.

Note 2: PPE must be used in accordance with manufacturer's instructions by appropriately trained personnel.

HOME WITHOUT HARM **BUILT ENVIRONS** **MCCONNELL DOWELL**